Partnership Learning

RISK ASSESSMENT

School: *The James Cambell Primary School*		**Date of Trip: N/A**
Activity: *Asbestos on Site*		**Location:** *Whole School*
People/Person at Risk: *Pupils/Staff/Visitors/Contractors*		**Emergency Contact Details :** *School Office 020 8270 4602/4684 Emergency Services 999*
Name of Person Completing Form: Caroline Stevens **Job Title: SBM** **Date: Sept 2026** **Signature:**  **Clara Breakwell - Headteacher**		**Next Review: Sept 2028**

Hazard	Risk	Initial Rating L, M, H	Existing Control Measures	Final Rating L, M, H	Additional Action Required (action by whom and completion date – use separate Action Plan if necessary)

Damage / deterioration to asbestos containing material releasing fibres into the atmosphere.	Asbestosis, mesothelioma, pleural thickening lung cancer	*H*	• Copy of asbestos survey, permission to work (PTW) and all related documentation retained on the school premises in the asbestos log. • All employees are aware of its location and content. School management and asbestos authorising officers also aware of all areas which were beyond the scope of the survey e.g. ceiling voids. • **No one**, staff or contractors must carry out invasive work without reference to the survey. • Asbestos log is consulted at the planning stage for **all** projects in order location of any asbestos or areas which were not surveyed can be confirmed. • Site Supervisors, contractors and others must read and sign the PTW log before commencing **any work** on the fabric of the building. • All such work on fabric of building authorised by a schools 'Authorising Officer'. • Where there is any doubt about whether a substance or structure may contain asbestos, then no work can be undertaken. Contact the local authority • Minimum of 2 (ideally 3), authorising Officers available on site (Those conducting the work cannot authorise their own permission to work) • Refresher training undertaken by asbestos authorised officers on a 3 yearly basis. • If there is any suggestion of contamination of a particular area then (1) inform the premises manager, (2) evacuate the area,	*L*	

			(3) seal it off and (4) contact local authority/PLT • Where ACM's have been assessed as satisfactory to leave intact an annual visual inspection of the asbestos remaining in situ is conducted by a schools authorising officer.		

Signed:-  Headteacher Date: 9/11/2026